

File: S530050

UTAH 3809 COMPLIANCE INSPECTION REPORT

Contract: U-74914

Field Office: UT-100

Operator(s): Stephen Laub

Project name: Dolomite-marble

Location: T39S R19W Sec 10 NWNW

Disturbance: Disturbed area is less than 0.5 acres total, consisting of an access road (0.2 acres) and open-cut/bulldozed area (0.2 acres). Prospect is in contact metamorphosed Callville Limestone (marble/dolomite) adjacent to the Mineral Mountain rhyolitic intrusion. The site is within Butcher Knife Canyon in one of the few areas not burned in the Bull Complex Fire.

Hazardous Materials on Site: None/The site is stable and fairly clean with a limited amount of trash on site.

Comments: Mr. Laub has reclaimed the road to his prospect from an old camp area. The road up Butcher Knife was repaired and is now open to the prospect. He reported that he had reseeded the prospect area last year.

Instructions to Operator: Send letter stating reclamation complete.

Recommended Action(s): Contact UDOGM.

Photographs Taken: See photographs below.

Russell Schreiner
Inspector: Russell Schreiner

Date of Inspection: May 30, 2007

Reviewed by: James D. Crisp
Jim Crisp, FM, St. George Field Office

Date: 06/07/07

RECEIVED

JUN 11 2007

DIV. OF OIL, GAS & MINING



Overview of the Laub Dolomite site.



Close up of small open-cut (5 ft wide by 30 ft long) in re-crystallized dolomite/marble, showing Indian ricegrass re-vegetation with Mr. Stephen Laub.



Close-up of penstemon and indian ricegrass.



View of the access road and the dozer-cut to the south before reclamation.



View of the access road at the dozer-cut to the south after reclamation



View of the access road, looking northeast.



View of the beginning of the access road reclamation at the camp out area.



View of typical reclamation work near the middle of the access road.